

bellies that continues for 61.8 feet between building H and B (noted by continued ( ) along sewer line).

Building B – no issues found

Building C – at 25 feet from the cleanout between building A and C there is root intrusion (marked by x on line running laterally between buildings A and C).

Building D - was accessed via roof vent - no issues found

Building E – was accessed at clean out at end of branch line on south side of building. At approximately 40 feet from the cleanout on the south side there is root intrusion. There is additional root intrusion at approximately 50 feet. (marked by x on line between building and main line)

Building F – was accessed through clean out. There is root intrusion from the south side of the building at approximately 10 feet. Additionally, there is root intrusion at 30 feet, located between building F and G. There is bellying of the line at approximately 80 feet continuing until the line intersects the main line running North to South

Building G – accessed from pulled toilet. At 60 feet from the clean out located on the east side, heading south, there is root intrusion. There is root intrusion at 42 feet further down the same line and at 52 feet.