

Area No.	Homogeneous Areas
----------	-------------------

<u>1</u>	1 x 1 Foot, Smooth Cream Floor Tile	Sampling Info
<u>2</u>	1 x 1 Foot, Smooth Beige/Tan Floor Tile	Sampling Info
<u>3</u>	TAR-LIKE BLACK PIPE COVERING	Sampling Info
<u>4</u>	FIBEROUS White Mudded Pipe Fittings	Sampling Info
<u>5</u>	Smooth White Drywall system	Sampling Info
<u>6</u>	1 x 1 Foot, Smooth Brown, LT BROWN Floor Tile	Sampling Info

****Note: If Positive, then at least one sample was analyzed as containing ACBM within the building.**

FM Program

Home

Building Info

Homogeneous Area Information

State ID 00814 **Date of Inspection** 12/8/1992
Building Name TROOP L HEADQUARTERS **Positive**
Accredited Building Inspector JOSEPH RID
LADEQ Accreditation No. 3I0438
Imminent Hazard Samples 1
Total Samples Collected 1

Sample Location Information

Sample No.	H.A. No.	Floor No.	Room No.	Location within Room
001	1	1	125	SOUTH AREA

Sample Laboratory Results

Sample No.	H.A. No.	Result	ASBESTOS					Non-ASBESTOS		
			Chry.	Amos.	Croc.	Other	Total	Synth.	F/G	Cell
001	1	POSITIVE	2-4%	ND	ND	Other	2-4	ND	ND	TR

FM Program

Home

Building Info

Homogeneous Area Information

State ID 00814 **Date of Inspection** 12/8/1992
Building Name TROOP L HEADQUARTERS **Positive**
Accredited Building Inspector JOSEPH RID
LADEQ Accreditation No. 3I0438
Imminent Hazard Samples 1
Total Samples Collected 1

Sample Location Information

Sample No.	H.A. No.	Floor No.	Room No.	Location within Room
002	2	1	127	SOUTH AREA

Sample Laboratory Results

Sample No.	H.A. No.	Result	ASBESTOS						Non-ASBESTOS		
			Chry.	Amos.	Croc.	Other	Total	Synth.	F/G	Cell	Non-Fib
002	2	POSITIVE	2-4%	ND	ND	Other	2-4	ND	ND	ND	

FM Program

Home

Building Info

Homogeneous Area Information

State ID 00814 **Date of Inspection** 12/8/1992
Building Name TROOP L HEADQUARTERS **Positive**
Accredited Building Inspector JOSEPH RID
LADEQ Accreditation No. 3I0438
Imminent Hazard Samples 1
Total Samples Collected 1

Sample Location Information

Sample No.	H.A. No.	Floor No.	Room No.	Location within Room
003	3	1	119	NORTH AREA

Sample Laboratory Results

Sample No.	H.A. No.	Result	ASBESTOS					Non-ASBESTOS		
			Chry.	Amos.	Croc.	Other	Total	Synth.	F/G	Cell
003	3	POSITIVE	5%	ND	ND	Other	5%	ND	5%	20%

FM Program

Home

Building Info

Homogeneous Area Information

State ID	00814	Date of Inspection	12/8/1992
Building Name	TROOP L HEADQUARTERS		Negative
Accredited Building Inspector	JOSEPH RID		
LADEQ Accreditation No.	3I0438		
Imminent Hazard Samples	0		
Total Samples Collected	3		

Sample Location Information

Sample No.	H.A. No.	Floor No.	Room No.	Location within Room
004	4	1	119	NORTHWEST AREA
005	4	1	119	NORTHWEST AREA
006	4	1	119	NORTHWEST AREA

Sample Laboratory Results

Sample No.	H.A. No.	Result	ASBESTOS						Non-ASBESTOS		
			Chry.	Amos.	Croc.	Other	Total	Synth.	F/G	Cell	Non-Fib
004	4	NEGATIVE	ND	ND	ND	Other	ND	ND	2-4%	20%	
005	4	NEGATIVE	ND	ND	ND	Other	ND	ND	5%	20%	
006	4	NEGATIVE	ND	ND	ND	Other	ND	ND	5%	20%	

FM Program

Home

Building Info

Homogeneous Area Information

State ID	00814	Date of Inspection	12/8/1992
Building Name	TROOP L HEADQUARTERS	Result	Negative
Accredited Building Inspector	JOSEPH RID		
LADEQ Accreditation No.	3I0438		
Imminent Hazard Samples	0		
Total Samples Collected	7		

Sample Location Information

Sample No.	H.A. No.	Floor No.	Room No.	Location within Room
007	5	A	119	SOUTHWEST AREA
008	5	A	119	NORTH AREA
009	5	A	119	NORTHWEST AREA
010	5	A	119	SOUTHEAST AREA
011	5	A	119	SOUTHEAST AREA
012	5	1	H136	SOUTH AREA
013	5	1	137	WEST AREA NEAR COLUMN

Sample Laboratory Results

Sample No.	H.A. No.	Result	ASBESTOS					Non-ASBESTOS			
			Chry.	Amos.	Croc.	Other	Total	Synth.	F/G	Cell	Non-Fib
007	5	NEGATIVE	ND	ND	ND	Other	ND	ND	ND	15%	
008	5	NEGATIVE	ND	ND	ND	Other	ND	ND	ND	TR	
009	5	NEGATIVE	ND	ND	ND	Other	ND	ND	ND	15%	
010	5	NEGATIVE	ND	ND	ND	Other	ND	ND	2-4%	2-4%	
011	5	NEGATIVE	ND	ND	ND	Other	ND	ND	ND	20%	
012	5	NEGATIVE	ND	ND	ND	Other	ND	ND	ND	10%	
013	5	NEGATIVE	ND	ND	ND	Other	ND	ND	ND	25%	

FM Program

Home

Building Info

Homogeneous Area Information

State ID 00814 **Date of Inspection** 12/8/1992
Building Name TROOP L HEADQUARTERS **Positive**
Accredited Building Inspector JOSEPH RID
LADEQ Accreditation No. 3I0438
Imminent Hazard Samples 1
Total Samples Collected 1

Sample Location Information

Sample No.	H.A. No.	Floor No.	Room No.	Location within Room
014	6	1	137	NORTHWEST AREA

Sample Laboratory Results

Sample No.	H.A. No.	Result	ASBESTOS						Non-ASBESTOS		
			Chry.	Amos.	Croc.	Other	Total	Synth.	F/G	Cell	Non-Fib
014	6	POSITIVE	2-4%	ND	ND	Other	2-4	ND	ND	TR	