

A photograph of a concrete floor slab showing several cracks. A red safety tape is applied in an L-shape across the lower portion of the slab. A red arrow points from a text box to one of the cracks. The floor is polished and reflects light. A black metal strip is visible along the top edge, and a white wall is on the left.

Cracks in slab

2023/11/01 14:26:46