



SERVICE PARTS

ITEM NO.	PART NO.	QTY.	DESCRIPTION	SPECIFICATIONS
1	61202 ■ ‡	1	Air Control Assembly	
2	61808 ■ ‡	1	Touch Transmitter	
3	106060 ■ §	1	Spa Harness Assembly	
4	106683 ■ §	1	Support System	
5	61807 ■	1	Spa Surround	
6	61805 ■ ‡	4	Jet Assembly	
7	61259 ■ ‡	1	Suction Assembly	
8	61699 ■ ‡	1	Filter and Grille Assembly	

SERVICE KITS

NOTES

- Parts Further Exploded Within This Catalog. Reference Index.
- ‡ Specify Finish.
- § Reference Number Only.