STRATUM ENGINEERING, LLC

Report of Timber Pile Inspection

Client: St. Tammany Fire Protection District No. 1
Chief Chad Duffaut
522 Robert Boulevard
Slidell, LA 70458

Project: Fire Station No. 10 - Lakeshore Vista Boulevard, Slidell, Louisiana

Work Order Date: 05/11/2026 **Project No:** C26-024

Report Date: 05/18/2026 **Work Order No:** 57875 **Report No:** 003

Our representative inspected treated timber piles for the above referenced project.
Results of the inspection are presented below:

Supplier: Desoto Treated Materials

Location of Inspection: Wiggins, Mississippi

Specification: _____ Length of Piles: 30 feet

Minimum Tip Diameter: 6 inches Minimum Butt Diameter: 8 inches @ Butt

Treatment Required: 0.80 lbs./ft. Treatment Analysis: 0.818, 0.836, 0.845, 0.869, 0.851, 0.823 lbs./ft

Number of pieces inspected today: 181

Number of pieces accepted today: 169

Number of pieces rejected today: 12

Hammer: NIS-2 Inspector: Robert Pierre

Technician: Robert Pierre

1-ec Dammon Engineering Attn: Mr. Chuck Dammon
1-ec Dynamic Constructors, LLC Attn: Mr. Jeff Hymel
1-ec Dynamic Constructors, LLC
Attn: Mr. Justin Wilkes
1-ec St. Tammany Fire Protection District No. 1
Attn: Chief Chad Duffaut
1-cc Laboratory

Respectfully Submitted,
Stratum Engineering, LLC

Robert Fowler, Senior Project Manager

THIS REPORT APPLIES ONLY TO THE STANDARDS OR PROCEDURES INDICATED AND TO THE SAMPLE(S) TESTED AND/OR OBSERVED AND ARE NOT NECESSARILY INDICATIVE OF THE QUALITIES OF APPARENTLY IDENTICAL OR SIMILAR PRODUCTS OR PROCEDURES, NOR DO THEY REPRESENT AN ONGOING QUALITY ASSURANCE PROGRAM UNLESS SO NOTED. THESE REPORTS ARE FOR THE EXCLUSIVE USE OF THE ADDRESSED CLIENT AND ARE NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION.