

### Report of Timber Pile Inspection

**Client:** St. Tammany Fire Protection District No. 1  
 Chief Chad Duffaut  
 522 Robert Boulevard  
 Slidell, LA 70458

**Project:** Fire Station No. 10 - Lakeshore Vista Boulevard,  
 Slidell, Louisiana

**Report Date:** 05/26/2026

**Work Order Date:** 05/22/2026

**Project No:** C26-024

**Work Order No:** 57945

**Report No:** 010

Our representative inspected treated timber piles for the above referenced project.  
 Results of the inspection are presented below:

**Supplier:** Desoto Treated Materials

**Location of Inspection:** Wiggins, Mississippi

**Specification:** \_\_\_\_\_ **Length of Piles:** 30 feet

**Minimum Tip Diameter:** 6 inches **Minimum Butt Diameter:** 8 inches @ Butt

**Treatment Required:** 0.80 lbs./ft. **Treatment Analysis:** 0.876 lbs./ft.

**Number of pieces inspected today:** 2

**Number of pieces accepted today:** 2

**Number of pieces rejected today:** 0

**Hammer:** NIS-2 **Inspector:** Robert Pierre

**Technician:** Robert Pierre

Respectfully Submitted,  
 Stratum Engineering, LLC



Robert Fowler, Senior Project Manager

**Report of Timber Pile Inspection**

**Client:** St. Tammany Fire Protection District No. 1  
Chief Chad Duffaut  
522 Robert Boulevard  
Slidell, LA 70458

**Project:** Fire Station No. 10 - Lakeshore Vista Boulevard,  
Slidell, Louisiana

**Report Date:** 05/26/2026

**Work Order Date:** 05/22/2026

**Project No:** C26-024

**Work Order No:** 57945

**Report No:** 010

1-ec Dammon Engineering Attn: Mr. Chuck Dammon  
1-ec Dynamic Constructors, LLC Attn: Mr. Jeff Hymel  
1-ec St. Tammany Fire Protection District No. 1  
Attn: Chief Chad Duffaut  
1-ec Dynamic Constructors, LLC  
Attn: Mr. Justin Wilkes  
1-ec Dynamic Constructors, LLC  
Attn: Reports Office  
1-cc Laboratory

**Technician:** Robert Pierre

Respectfully Submitted,  
Stratum Engineering, LLC



Robert Fowler, Senior Project Manager